

The following data reflects test results from tests performed by Tom Frankel, independently of Commercial Water Distributing, LLC:

Test Type: EPA-Based WaterSafe Coliform Bacteria Test

Purpose: To determine the presence of bacteria in water. A positive result indicates that your water may be contaminated with bacteria that can be harmful to your health or cause disease.

Results Key:

Yellow Color: Positive Result



Purple color: Negative Result (No bacteria were detected).



Test Type: EPA-Based WaterSafe Coliform Bacteria Test

Test Date: 11/29/2014

Test Location: Rochester, MN

Test Time: 9:20am

Water Source: River (South Fork Zumbro River)

Source Location: 44.046022, -92.464296

Filtration Used: NONE

Model If Applicable: NONE

Results: POSITIVE

Supporting Images:



Test Type: EPA-Based WaterSafe Coliform Bacteria Test

Test Date: 11/29/2014

Test Location: Rochester, MN

Test Time: 9:30am

Water Source: River (South Fork Zumbro River)

Source Location: 44.046022, -92.464296

Filtration Used: Yes

Model If Applicable: Merlin Eco-Solutions Water Purifier

Supporting Images:



The following data reflects test results from tests performed by Tom Frankel, independently of Commercial Water Distributing, LLC:

Test Type: EPA-Based WaterSafe Coliform Bacteria Test

Purpose: To determine the presence of bacteria in water. A positive result indicates that your water may be contaminated with bacteria that can be harmful to your health or cause disease.

Results Key:

Yellow Color: Positive Result



Purple color: Negative Result (No bacteria were detected).



Test Type: EPA-Based WaterSafe Coliform Bacteria Test

Test Date: 11/29/2014

Test Location: Rochester, MN

Test Time: 9:35am

Water Source: Pond (Quarry Hill Nature Center)

Source Location: 44.030721, -92.431457

Filtration Used: NONE

Model If Applicable: NONE

Results: POSITIVE

Supporting Images:



Test Type: EPA-Based WaterSafe Coliform Bacteria Test

Test Date: 11/29/2014

Test Location: Rochester, MN

Test Time: 9:40am

Water Source: Pond (Quarry Hill Nature Center)

Source Location: 44.030721, -92.431457

Filtration Used: Yes

Model If Applicable: Merlin Eco-Solutions Water Purifier

Results: NEGATIVE

Supporting Images:

